

**EUROPEAN AVIATION SAFETY AGENCY**  
**MASTER MINIMUM EQUIPMENT LIST - LISTE PRINCIPALE D'ÉQUIPEMENT MINIMAL**

<b>Aircraft – Aéronef</b> Canadair BD100-1A10	Temporary Revision No. 3	<b>TR# 3</b> <b>Page</b> 1 of 3
	<b>Date:</b> Feb 8/11	

**TEMPORARY REVISION No 3**

**LETTER OF TRANSMITTAL**

REASON FOR ISSUE:

The MMEL Temporary Revision 3 is based on EASA accepted Temporary Revision Submission (TRS) No. 3.

TRS No.3 provides MMEL dispatch relief for the EMTEQ LED EXIT identifiers that passed illumination tests (P/N C300-ELES-001 and C300-ELES-002).

INSTRUCTIONS FOR INSERTION OF THIS TEMPORARY REVISION:

- (1) Insert the Record of Temporary Revisions in the front portion of the MMEL supplement.
- (2) Insert the pages of this Temporary Revision in the MMEL supplement as instructed at the top of the page.
- (3) Record the insertion of this Temporary Revision on the Record of Temporary Revision page.
- (4) Retain this page for record purposes.

LIST OF PAGES AFFECTED BY THIS TEMPORARY REVISION

TpRv-1  
33-5

**EUROPEAN AVIATION SAFETY AGENCY**  
**MASTER MINIMUM EQUIPMENT LIST - LISTE PRINCIPALE D'ÉQUIPEMENT MINIMAL**

<b>Aircraft – Aéronef</b> Canadair BD100-1A10	Temporary Revision No. 3	<b>TR# 3</b> <b>Page</b> 2 of 3
	<b>Date:</b> Feb 8/11	

**RECORD OF TEMPORARY REVISIONS**

Retain this index in the front of the manual. When Temporary Revisions are issued or cancelled, enter the date you insert each revision in your manual.

**INSERT IN MMEL  
 FACING PAGE TPR-1**

Temp Rev#	Pages Affected	JAA approval	Description of Revision	Date Incorporated Signature
3	33-5	TRS No 3 was accepted by Colin Hancock, EASA MMEL Section Manager for and on behalf of the EASA. on 10-Dec-2010	To provide MMEL dispatch relief for the EMTEQ LED EXIT identifiers that passed illumination tests (P/N C300- ELES-001 and C300-ELES- 002).	

**EUROPEAN AVIATION SAFETY AGENCY**  
**MASTER MINIMUM EQUIPMENT LIST - LISTE PRINCIPALE D'ÉQUIPEMENT MINIMAL**

<b>Aircraft – Aéronef</b> Canadair BD100-1A10	Temporary Revision No. 3	<b>TR# 3</b> <b>Page</b> 3 of 3
	<b>Date:</b> Feb 8/11	

**TEMPORARY REVISION No 3**

**INSERT IN MMEL  
 IN FRONT OF PAGES 33-5**

1. System & Sequence No N° de système/série article				2. Number Installed Nombre d'article installés
				3. Number Required For Dispatch Nombre d'articles à expédier
				4. Remarks or Exceptions Remarques ou exceptions
<b>33 – LIGHTS</b>				
50-02 Exit Identifiers and Emergency Escape Path Marking System (Seat Mounted Lighting System)		1	1	System must be operative
1) Path Marking Light Fixtures (Bruce Industries Lights STC ST01569LA)	C	-	-	A minimum of one out of two bulbs in each fixture must be operative.
2) Exit Identifiers				
a) Bruce Industries Light Model BR9661-series STC ST01569LA	C	2	2	A minimum of two out of five bulbs within each fixture must be operative.
b) EMTEQ LED type (P/N C300-ELES-001 and C300-ELES-002 only)	C	3	3	A minimum of three full LED rows out of four within each fixture must be operative.